

What is the measurement range & sensor standoff distance required?

Key Concept –

Probe standoff, at the center of the measurement range, is equal to total measurement range

